



DIAMOND MOUNTAIN RA 3809 FIELD INSPECTION FORM

DATE: 10/13/94 TIME: 0930 LOCATION: T.3S, R.21E, Sec.29, Subdivision NWNW (SLB&M)

OPERATORS PRESENT DURING INSPECTION: None

SERIAL NO. OF NOTICE/PLAN ON FILE: U-66366 IS OPERATION ACTIVE? No

DESCRIPTION OF OPERATIONS (including access, reclamation, etc.):

D.J. Beaupeurt-Schantz, Diamond Mountain RA PST, and Wayne Stevens, BLM District Enforcement Ranger, inspected the site on this date (10/13/94). There has been no activity at this site since the 4/3/92 inspection. The project area still consists of an open shaft (appx. 18 ft. deep), with a deteriorated "walkway" across the western side and some rotted timbers which have fallen into the shaft area. The shaft appears to be gradually sloughing in. The make-shift wire fencing with the "Danger: Open Shaft" sign is still in place. It appears to be keeping miscellaneous animals and people out of the open shaft area. The pile of several wooden plank-type materials is still in place at the western end of the claim area. Natural vegetation is growing in and around the area. Dirt piles are still located along the rim of the shaft. The unauthorized roadway has not been recently used.

OTHER KNOWN PERMITS: None

IS THE OPERATION IN COMPLIANCE WITH THE NOTICE ON FILE AND/OR THE STIPULATIONS OF THE APPROVED PLAN? YES If NO describe deficiencies:

Although no improvements have been made to the fence around the open shaft, it appears to be adequate at this time. No erosion was noted outside of the actual shaft. No explosives were noted.

|            | Signature                     | Print Name/Title                      | Date     |
|------------|-------------------------------|---------------------------------------|----------|
| Inspector  | <i>D.J. Beaupeurt-Schantz</i> | D.J. Beaupeurt-Schantz, Phys Sci Tech | 10/13/94 |
| Management | <i>Ron Trogstad</i>           | Ron Trogstad, Area Manager, Area Mgr  | 10/13/94 |

Attachments: Photographs of open shaft area.

Advise ORCA/CRS data entry specialist of inspection for data entry |\_\_|, date:  
If operation is in noncompliance, issue notice of noncompliance within 5 working days |\_\_|

Distribution:

1. Original to Surface Management File
2. Tony Gallegos, Reclamation Engineer  
State of Utah  
Division of Oil, Gas and Mining  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, UT 84180-1203

# S047051